



Folding Table 750

Hardware List:	Bolt M6x40 / washer / nut	21
	Lock	2
	Rubber Plug	4



Step 1, Draw 2 lines for the 2 side legs. Put the side leg align the line and drill 8 holes. Fasten 8 bolts M6*40 with washers and nuts.

When drill holes for the bolts, make sure to put a wood board underneath, otherwise the table top will split



Step 2, make the side leg vertical in 90 - 91 degree and then position the lock. Drill hole for the lock and 2 bolts M6*40. Fasten the bolts with washers and nuts



Step 3. Repeat another side leg. Mount 4 rubber plugs.